

SECOR INTERNATIONAL INCORPORATED www.secor.com

2655 Camino Del Rio N. Suite 302 San Diego, CA 92108 619-296-6195 TEL 619-296-6199 FAX

DATE: April 5, 2005

ARCO QUARTERLY STATUS REPORT

Facility No.: <u>5512</u> Address: ARCO Environmental Engineer:

9606 Winter Gardens Boulevard, Lakeside, CA Roy Thun

CAP

Consulting Co./Contact Person:

SECOR/Marci Richards and Kurt Myers

Consulting Co./Contact Person:

NODD LIEE 12 DE

SECOR Project No.:

Current Phase of Project:

08BP.U5512.05

Primary Agency/Regulatory ID No.:

County of San Diego Site Assessment and Mitigation (SAM) Program Case # H26488-001 (Danny Martinez)

(Assmnt, Remed., etc.)

WORK PERFORMED THIS QUARTER [First - 2005]:

- 1. Submitted fourth quarter 2004 status report.
- 2. Prepared to destroy the monitoring wells at the site.

WORK PROPOSED FOR NEXT QUARTER [Second - 2005]:

- 1. Submit first quarter 2005 status report.
- 2. Destroy the monitoring wells at the site.

Frequency of Sampling:	None	(Quarterly, etc.)	
Frequency of Monitoring:	None	(Monthly, etc.) STERED GEOLO	
Are Liquid Phase Hydrocarbons Present On-site:	No	(Yes/No) 1700 Pro 3:31 - 00	
Cumulative LPH Recovered to Date:	None	(gallons) Cert. Eng. Geologist	
LPH Recovered This Quarter:	None	(gallons)	
Bulk Soil Removed to Date:	None	(cubic yards)	
Bulk Soil Removed This Quarter:	None	(cubic yards)	
Water Wells or Surface Waters w/in a 2000 ft. Radius & Their Respective Directions:	One irrigation well located approximately 1,880 feet upgradient (south)	(Distance and direction)	
Current Remediation Techniques:	None	(SVES, LPH Removal, etc.)	
Permits for Discharge:	None	(NPDES, POTW, etc.)	
Approximate Depth to Groundwater:	Not measured this quarter	(Measured Feet)	
Groundwater Gradient:	Not determined this quarter	(Direction)	
	Not determined this quarter	(Magnitude)	

DATE: April 5, 2005

ARCO QUARTERLY STATUS REPORT (Continued) ARCO Facility #5512

DISCUSSION: During the first quarter 2005, SECOR prepared the fourth quarter 2004 status report and prepared to destroy the monitoring wells at the site. During the second quarter 2005, SECOR will submit the first quarter 2005 status report and destroy the monitoring wells at the site.

CONCLUSIONS & RECOMMENDATIONS: SECOR recommends destroying the monitoring wells at the site.

SUMMARY OF UNUSUAL ACTIVITY:	None
AGENCY DIRECTIVE REQUIREMENTS:	None

cc: Mr. Roy Thun - Atlantic Richfield Company